

Embraer 170 /175 Slat Harness Repair


Herber Aircraft Harness Benefits

Superior service life — longer repair/ replacement interval

Substantial savings over purchasing new harness (typically 60% of OEM price)

Replacements parts comparable or better than OEM

Quick 2 week repair time



171-00191-401 Slat Harness

While being exposed to the leading edge of the wing, slats and their components endure tremendous stresses including high pressures, varying temperatures, vibration, and corrosion. Routine repair and maintenance are essential to assure the structural integrity and performance reliability of the aircraft.

Herber Aircraft Service offers an FAA approved repair that delivers a superior harness with enhancements that exceed the quality, reliability and value of OEM products, extending service life as much as twice as long. With a quick two week repair time your aircraft will be back in service in no time reducing AOG time and costly delays.

Applications



Embraer 170



Embraer 175

OEM Part Number	Description
171-00191-401	Embraer 170/175 L/H Slat Harness