



HERBER AIRCRAFT SERVICE, INC.  
1401 E. Franklin Ave.  
El Segundo, CA. 90245 U.S.A.  
310-322-9575  
[www.herberaircraft.com](http://www.herberaircraft.com)

May 19, 2025

Dear Valued Customers,

With this update, Herber Aircraft Service intends to bring you up to date on our various engine harness offerings, along with some new products we're about to bring to market:

**CFM56-7B EGT "FAA-PMA" P/N TC296-03ACS (aircraft: B737-700/-800/-900 and P8-A)**

**Replacement for: P/N TC296-02, TC296-03, TC296-04, 340-402-503-0, 340-402-504-0, 340-402-505-0**

We deliver 800+ units annually to multiple airlines around the world. Our pricing and turnaround times are vastly superior to those of the OEM, and we also maintain finished goods of over 100 units, ready for same day shipment.



On all other CFM56-7B engine harnesses, Herber Aircraft offers repairs using OEM (CMM) data, and when necessary, repairs and overhauls when the scope is not covered by OEM data, using our FAA-approved Repair Specifications (aka DER). We maintain a component inventory valued at over half a million dollars to help minimize long manufacturer lead-times and get you back in service quickly.

**CF34-8E/C Engine Wiring Harness repair/overhaul capabilities (Bombardier CRJ, Embraer e-Jets, Comac ARJ21/C909)**

Herber Aircraft is the industry leader in CF34-8 Engine harness repairs. We can produce or repair parts in the absence of OEM availability, which would generally require the harness to be scrapped. Our superior harness enhancements exceed the quality and reliability of OEM products, extending service life as much as twice as long. Our quick turnaround time of 3 weeks helps reduce AOG time and other costly delays.



For the **PW2000 (B757), PW4000 (A300, A310, B747, B767, B777 and MD-11), CF6-80E1 (A330), V2500 (A320CEO) and CF6-80C2 (A300, A310, B747, B767, MD-11)**: we offer stock harnesses, repairs and various components, available for immediate shipment.

And debuting in mid-to-late 2025, Herber Aircraft will offer:

**GENx-1B EBU Wiring Harness repair/overhaul capabilities (B747-8, B787)**

**LEAP-1A/-1B Engine Wiring Harness repair/overhaul capabilities (B737-MAX, A320-NEO series)**

Herber Aircraft currently offers a cost-saving PMA harness replacement option to the OEM harness. We operate an MRO that is FAA, EASA, CAAC, and UK certified, with an expansive capability listing. Quick turnaround and AOG services are available with our 20+ assembler technicians at our main facility in El Segundo, CA, located one mile south of LAX. For more information, please visit our website and the dedicated portion on Harness products @ [https://www.Herber Aircraft Serviceaircraft.com/aircraft-wire-tube-harnesses](https://www.HerberAircraftServiceaircraft.com/aircraft-wire-tube-harnesses).

If you have any questions or are interested in the foregoing, please contact Walter Alvarez via the phone number or e-mail shown below.

Sincerely,  
**Herber Aircraft Service, Inc.**

Chris Chance  
Sr. Director Global Sales & Marketing  
[cchance@herberaircraft.com](mailto:cchance@herberaircraft.com)

Walter Alvarez  
Director of Business Development  
[walvarez@herberaircraft.com](mailto:walvarez@herberaircraft.com)  
T: 310.322.9575 M: 310.869.9340